

COPY OF PAPERS
ORIGINALLY FILED

100

110

F	F	F	F	F	F	3.3
F	F	F	F	F	F	3.3165
F	F	F	F	F	F	3.333
F	F	F	F	F	F	3.3495
F	F	F	F	F	F	3.366
F	F	F	F	F	F	F	3.3825
F	F	F	F	F	F	F	F	3.399
F	F	F	F	F	F	F	F	F	.	.	.	3.4155
F	F	F	F	F	F	F	F	F	F	.	.	3.432
F	F	F	F	F	F	F	F	F	F	F	.	3.4485
F	F	F	F	F	F	F	F	F	F	F	F	3.465
1	1	1	1	1	1	1	1	1	1	1	1	
7	7	7	7	7	7	7	7	7	7	7	8	
1	1	2	3	4	5	6	7	8	9			
9	8	7	6	5	4	3	2	1				

FIRST
OPERATION
PARAMETER

SECOND
OPERATION
PARAMETER

Fig. 1
Prior Art

BEST AVAILABLE COPY

```
StartPoint = ( 1.95000, 3.50000 )  
HorizontalStepSize = 0.05000      VerticalStepSize = 0.05000  
HorizontalRange = 1.00000 - 2.60000      VerticalRange = -2.00000 - 4.60000
```

250	F F F F F F F F F F	3.9000
	F F	3.8500
	F F	3.8000
	F F	3.7500
	F F	3.7000
	F F	3.6500
	F F	3.6000
	F F	3.5500
	F F	3.5000
	F F	3.4500
	F F	3.4000
	F F	3.3500
	F F	3.3000
	F F	3.2500
	F F	3.2000
	F F	3.1500
	F F	3.1000
	F F	3.0500
	F F	3.0000
	F F	2.9500
	F F	2.9000
	F F	2.8500
	F F	2.8000
	F F	2.7500
	F F	2.7000
	F F	2.6500
	F F	2.6000

First Operating Parameter

Points Tested - 130

210

Fig. 2

BEST AVAILABLE COPY

300




Fig. 3

BEST AVAILABLE COPY




Fig. 4